July 14, 2022

To whom it may concern:

Labcon is conducting a recall of the following products: <u>7626-500-000-9</u> and <u>7626-540-000-9</u>

<u>Product description:</u> U-pette dispenser <u>Lot numbers affected</u>: any lot number with 2 in the position as highlighted below.

XXXC8-<mark>2</mark>XX

Purchase orders that are possibly affected: please see the list below

119387

<u>Reason for the recall</u>: While performing a product audit it was discovered that metal cannulas in the U-pette dispensers could occasionally get displaced when the dispenser is inserted in the Vacutainer stopper.

<u>Action required</u>: please check your inventory for the presence of the lot numbers mentioned above. Please contact the end-users if needed.

<u>Supplier contact for credit and/or replacement</u>: If any of these lots are found in your stock please contact <u>custsupport@labcon.com</u>

<u>CAPA statement</u>: A new testing protocol is implemented for U-pette cannula testing as of 07/14/2022

Please contact <u>custsupport@labcon.com</u> if you have any questions or concerns.

Lily Remennik Customer Support/QA Manager